
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/9/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S02CC1007MH	Test ID: <u>D1032-027009</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S02CC1007MH
0			Water Level	
10			Dye Test Visible	DYE SEEN AT JOINT
13.60000038			Dye Test Visible	DYE SEEN AT JOINT
16.70000076			Dye Test Visible	DYE SEEN AT JOINT
31.29999924			Abandoned Survey	DYE TEST IS COMPLETE